



MANUFACTURE OF STRAIN GAUGES & TRANSDUCERS

- **We produce sensors fitted with semiconductor or metal strain gauges for measuring forces, mass, pressure, torque, acceleration.**
- **We supply semiconductor silicon strain gauges, which have the highest known efficiency of the transfer of mechanical quantities to electrical signal.**
- **When designing and manufacturing sensors and transducers, we apply experience well-proved in the aerospace industry.**



CONTENT OF CATALOG

COMPANY INTRODUCTION	2
PRINCIPLE OF OUR SENSORS	3
TRANSDUCERS	4
Sensors for measuring tensile forces and pressure – type „S“	5
Sensors for measuring tensile forces and pressure - membrane	6
Sensors for small pressure	7
Robust sensors	8
Sensors for pressure - cylinder with a hemisphere.....	9
Bending beam.....	10
Pressure sensors.....	11
Sensors for measuring the relative deformation of the material	12
Rope tension sensors	12
Sensor of torque, Screwdriver, Wrench	13
SEMICONDUCTOR STRAIN GAUGES	14
Code designation and admeasurement of strain gauges.....	15
The range of semiconductor strain gauges	16
Basic mathematical equations	18
SAMPLES OF SOME TRANSDUCERS.....	20
INDIVIDUAL APPLICATION OF STRAIN GAUGES	22



Our company was established at the beginning of 1990 in order to ensure the flexible development of semiconductor strain gauges and their applications under new economic conditions. It associated experts who had developed manufacturing technology at the The Aeronautical Research and Test Institute in Prague as well as specialists who had run the production of gauges since its start at OPS, Zlín. This manufacture, established there in 1974 for the aerospace industry, had to be increased eightfold for other industries by 1978, and twentyfold by 1989 for export needs.

CONTACTS

Invoice and mailing address:

VTS Zlin s.r.o.
tr.Tomase Bati 5146
CZ-76001 Zlin
Czech Republic

GPS: 49°13'16.51"N, 17°39'10.793"E

ID-Nr.: 03173534

VAT: CZ03173534


Phone: +420 577 217 171




Fax.: +420 577 217 172

E-mail: info@vtsz.cz


The function of a semiconductor strain gauge essentially consists in a very considerable and accurate change in its electrical resistance with applied mechanical strain. Sensors with these elements give to all mechanisms the ability to respond sensitively to mechanic impulses. They are usually used for force, mass, pressure, torque, acceleration and deformation electric measurements.

Basic principles:




PRESSURE		TORQUE
0.01 MPa – 5 MPa	5 Mpa – 100 MPa	0.01 N.m – 100 N.m
		

The most common use of strain gauges is for half-bridge or full-bridge, because during statical measurements it compensates the temperature effects. Measurement of electric resistance of one strain gauge can be used only there, where we don't need to compensate the temperature effects.



Full-bridge circuit



Half-bridge circuit

Technical merits of semiconductor as compared with wire and foil strain gauges:

- ✓ 60x higher strain sensitivity allowing measurement without amplifiers, with standard ohmmeters and voltmeters (input current 10mA , output voltage tens mV).
- ✓ 60x higher threshold sensitivity making possible measurement of strain in metals beginning with a value as low as a millionth of one millimetre per metre.
- ✓ Small width of strain gauges enabling the design of small and light sensors.
- ✓ Results of stress analysis of parts that can be subjected to controlled heating are absolutely reliable.
- ✓ Up to 300°C, monocrystalline silicon strain is without measurable hysteresis Strain gauges made of silicon and gold possess outstanding corrosion resistance.



MANUFACTURE OF STRAIN GAUGES & TRANSDUCERS

VÝROBA TENZOMETRŮ A SNÍMAČŮ ZLÍN

tr.Tomase Bati 5146 , CZ - 76001 Zlin , Czech Republic

Phone: +420 577 217 171 , Fax: +420 577 217 172 , E-mail: info@vtsz.cz

www.vtsz.cz

TRANSDUCERS



We produce sensors according to customer requirements.

- **Our sensors are suitable for measuring forces, mass, pressure, torque, acceleration.**
- **Accuracy of sensors (non-linearity + hysteresis) with semiconductor strain gauges we guaranteed to $\pm 0.5\%$ of the nominal range.**
- **Safe overload sensor is to 200% nominal range.**
- **We can use foil strain gauges from other company in sensors.**

Typical characteristics of our transducers:



	UNIT	VALUE
Input current	mA	10 – 30
Rated unloaded signal (the difference between output signal of 100% loaded and free sensor) at power $I_{in}=10\text{mA}$	mV	50 ± 0.2
Output signal of free sensor at power $I_{in}=10\text{mA}$	mV	0 ± 0.2
Output signal of loaded sensor at the nominal value at input current 10mA	mV	50 ± 0.2
Combining error (non-linearity + hysteresis) – in % of the nominal range sensor	%	$< \pm 0.5$
Safe overload	%	200
Long-term stability (in% of the nominal sensor range)	%	$< \pm 0.1$
Temperature coefficient of unloaded sensor signal	$\%/^{\circ}\text{C}$	< 0.01
Temperature coefficient of the output signal	$\%/^{\circ}\text{C}$	< 0.03
Operating temperature range	$^{\circ}\text{C}$	-10 až +40
Life in terms of number of cycles of the nominal load		$> 10^7$

Sensors for measuring tensile forces and pressure – type „S“



Type	Range [kg]	Height h [mm]	Weight w [mm]	Thickness t [mm]	Screw M [mm]
F025	0 - 10	50	50	20	5
F026	0 - 20	50	50	20	5
F027	0 - 50	50	50	20	8
F028	0 - 100	50	50	20	8
F029	0 - 250	65	50	20	12

* All parameters can be consulted and adjusted according to customer requirements.




Type	Range [kg]	Height h [mm]	Weight w [mm]	Thickness t [mm]	Screw M [mm]
F030	0 - 500	65	50	20	12
F031	0 - 1000	65	50	20	12
F032	0 - 2500	95	70	36	24
F033	0 - 5000	95	70	36	24

* All parameters can be consulted and adjusted according to customer requirements.

* This type of sensor is suitable for measuring tensile forces and pressure.

Sensors for measuring tensile forces and pressure - membrane






Sensor is provided with a screw also on the underside for measuring tensile force.

Type	Range [kg]	Note
F079	0 – 500	tensile + pressure
F088	0 – 1000	tensile + pressure
F123	0 – 2000	pressure

* All parameters can be consulted and adjusted according to customer requirements.

Sensors for small pressure






Type	Range [kg]	Connection
SRK1-V	0 – 100	bushing and cable
SRK1-K	0 – 100	connector

* All parameters can be consulted and adjusted according to customer requirements.


Robust sensors



Type	Range [kg]
SG16-5	0 – 500
SG16-10	0 – 1 000
SG16-20	0 – 2 000


Type	Range [kg]
SG16-30	0 – 3 000
SG16-50	0 – 5 000
SG16-100	0 – 10 000

* All parameters can be consulted and adjusted according to customer requirements.



Type	Range [kg]
SG-20	0 – 20 000
SG-30	0 – 30 000
SG-40	0 – 40 000

Sensors for pressure - cylinder with a hemisphere





Type	Range [kg]
F095	0 – 500
F096	0 – 1000





*** All parameters can be consulted and adjusted according to customer requirements.**

Bending beam

Option A:



Option B:





The design, shape and size of these sensors are variable. The sensors are designed and manufactured according to customer requirements. Sensors can be made from steel or alloy, in a different class of IP, etc.

Pressure sensors



PP-20




PP-1


Type	Range [Mpa]	Height [mm]	Diameter [mm]
PP-1	1.0	77.0	40.0
PP-2	2.0	77.0	40.0
PP-20	20.0	143.0	36.0
PP-30	30.0	103.0	36.0

Sensors for measuring the relative deformation of the material

TYP: E001
Rozsah: 0 - 500µm



Rope tension sensors



Type	Range [kg]	v [mm]	h [mm]	s [mm]
L016-2k	2 000	210	67 + thick rope	117 – for 3 ropes
L019-3k5	3 500	228	83 + thick rope	170 – for 6 ropes

Sensor of torque, Screwdriver, Wrench


We makes different types and ranges of torque sensor. As a standard types are calibrator torque, torque screwdriver and torque wrench.



Torque Wrench



Torque Screwdriver



Calibrator Torque

Type	Range	Description
TQ039	+/-1 Nm	torque Screwdriver (1/4")
TQ030	+/-5 Nm	torque Screwdriver (1/4")
TQ040	+/-5 Nm	torque Wrench (ráčna 1/4")
TQ020	+/-15 Nm	torque Wrench (ráčna 3/8")
TQ021	+/-60 Nm	torque Wrench (ráčna 1/2")
TQ022	+/-100 Nm	torque Wrench (ráčna 1/2")
TQ023	+/-150 Nm	torque Wrench (ráčna 1/2")
TQ024	+/-300 Nm	torque Wrench (ráčna 1/2")
TQ025	+/-600 Nm	torque Wrench (ráčna 3/4")
TQ026	+/-1.000 Nm	torque Wrench (ráčna 3/4")
TQ034	+/-20 Nm	calibrator torque
TQ033	+/-200 Nm	calibrator torque
TQ051	+/-600 Nm	calibrator torque

* All parameters and ranges can be consulted and adjusted according to customer requirements.



MANUFACTURE OF STRAIN GAUGES & TRANSDUCERS


VÝROBA TENZOMETRŮ A SNÍMAČŮ ZLÍN

tr. Tomase Bati 5146 , CZ - 76001 Zlin , Czech Republic


Phone: +420 577 217 171 , Fax: +420 577 217 172 , E-mail: info@vtsz.cz

www.vtsz.cz

SEMICONDUCTOR STRAIN GAUGES



without support



with support


At present, we have these types of strain gauges store: Type „Positive“, length 3mm and 6mm, with gauge factor $C_1 = 120 - 150$ and with electrical resistance 120 , 350 and 1000 Ohm. Of course, we are able to produce strain gauges with parameters according to customer's requirements.

We deliver semiconductor strain gauges in two sorts of tolerance at pack, specified by assurance of their tolerance characteristics. For dynamic measurement and stable temperatures are suitable strain gauges marked as **N-sort**. For static measurements, sensors and strain gauges for temperature fluctuation are suitable ones marked as **T-sort**.


		Tolerance at pack (standard is 5 pieces)		Tolerance of type	
		N-sort	T-sort	N-sort	T-sort
R_0 – Electrical resistance of the free gauge		$\pm 0.4\%$	$\pm 0.25\%$	$\pm 5\%$	$\pm 3\%$
R_B - Electrical resistance of the free gauge with support		$\pm 1\%$	$\pm 0.50\%$	$\pm 10\%$	$\pm 5\%$
Strain sensitivity constants	C_1 (Gauge factor)	$\pm 2\%$	$\pm 2\%$	$\pm 5\%$	$\pm 5\%$
	C_2	$\pm 8\%$	$\pm 8\%$	*	*
α - Temperature resistance coefficient of the free gauge		-----	$\pm 0.02\%/^{\circ}\text{C}$	-----	*
Limit static positiv tensile strain		0.3%	0.3%	0.3%	0.3%

* according to contract



Code designation of strain gauges






Dimensions of strain gauges



The range of semiconductor strain gauges

Implementation	Type	Nominal resistance [Ohm]	K-factor	Length of strain gauge L [mm]	
	AP95-3-3	30	+95	3	
	AP105-5-3	30	+105	5	
	AP120-1.5-12	120	+120	1.5	
	AP120-3-12	120	+120	3	
	AP120-6-12	120	+120	6	
	AP120-6-25	250	+120	6	
	AP120-10-12	120	+120	10	
	AP120-10-35	350	+120	10	
	AP125-2-12	120	+120	2	
	AP130-1.5-12	120	+130	1.5	
	AP130-3-12	120	+130	3	
	AP130-6-12	120	+130	6	
	AP130-6-35	350	+130	6	
	AP130-10-60	600	+130	10	
	AP130-20-35	350	+130	20	
	AP140-2-12	120	+140	2	
	AP140-3-35	350	+140	3	
	AP140-6-35	350	+140	6	
	AP140-10-100	1000	+140	10	
	AP150-1.5-35	350	+150	1.5	
	AP150-2-12	120	+150	2	
	AP150-3-55	550	+150	3	
	AP150-3-100	1000	+145	3	
	AP150-6-35	350	+150	6	
	AP160-1.5-35	350	+160	1.5	
	AP160-6-100	1000	+160	6	
	AP160-10-170	1700	+160	10	
		AN20-6-65	650	-20	6
		AN120-3-12	120	-120	3
	AN120-3-35	350	-120	3	
	AN120-6-30	300	-120	6	
	BP120-3-12	120	+120	3	
	BP120-6-12	120	+120	6	
	BP120-10-35	350	+120	10	
	BP130-1.5-12	120	+130	1.5	
	BP130-3-12	120	+130	3	
	BP130-6-35	350	+130	6	
	BP130-10-60	600	+130	10	
	BP140-3-35	350	+140	3	
	BP140-10-100	1000	+140	10	
	BP150-1.5-35	350	+150	1.5	

	BP150-3-100	1000	+150	3
	BP150-6-100	1000	+150	6

Implementation	Type	Nominal resistance [Ohm]	K-factor	Length of strain gauge L [mm]
	CP120-3-12-G	120	+120	3
	CP120-6-12-G	120	+120	6
	CP120-10-35-G	350	+120	10
	CP130-1.5-12-G	120	+130	1.5
	CP130-3-12-G	120	+130	3
	CP130-6-35-G	350	+130	6
	CP130-10-60-G	600	+130	10
	CP140-3-35-G	350	+140	3
	CP140-10-100-G	1000	+140	10
	CP150-1.5-35-G	350	+150	1.5
CP150-3-100-G	1000	+150	3	
CP150-6-100-G	1000	+150	6	
	DP120-3-12-G	120	+120	3
	DP120-6-12-G	120	+120	6
	DP120-10-35-G	350	+120	10
	DP130-1.5-12-G	120	+130	1.5
	DP130-3-12-G	120	+130	3
	DP130-6-35-G	350	+130	6
	DP130-10-60-G	600	+130	10
	DP140-3-35-G	350	+140	3
	DP140-10-100-G	1000	+140	10
	DP150-1.5-35-G	350	+150	1.5
DP150-3-100-G	1000	+150	3	
DP150-6-100-G	1000	+150	6	
	EP120-3-12-G	120	+120	3
	EP120-6-12-G	120	+120	6
	EP120-10-35-G	350	+120	10
	EP130-1.5-12-G	120	+130	1.5
	EP130-3-12-G	120	+130	3
	EP130-6-35-G	350	+130	6
	EP130-10-60-G	600	+130	10
	EP140-3-35-G	350	+140	3
	EP140-6-35-G	350	+140	6
	EP140-10-100-G	1000	+140	10

EP150-1.5-35-G	350	+150	1.5
EP150-3-100-G	1000	+150	3
EP150-6-100-G	1000	+150	6



MANUFACTURE OF STRAIN GAUGES & TRANSDUCERS


VÝROBA TENZOMETRŮ A SNÍMAČŮ ZLÍN

tr. Tomase Bati 5146, CZ - 76001 Zlin, Czech Republic

Phone: +420 577 217 171, Fax: +420 577 217 172, E-mail: info@vtsz.cz

www.vtsz.cz

BASIC MATHEMATICAL EQUATIONS



For free gages (without support):

Dependence of resistance to deformation:

$$R_{\varepsilon,25} = R_{0,25} \cdot (1 + C_1 \cdot \varepsilon + C_2 \cdot \varepsilon^2) \quad (1)$$

Dependence of resistance to temperature:

$$R_{0,t} = R_{0,25} \cdot (1 + a(t - 25) + b(t - 25)^2) \quad (2)$$

Dependence of resistance to deformation and temperature:

$$R_{\varepsilon,t} = R_{0,t} + R_{0,25} \left[C_1 (\varepsilon + (\alpha_{mat} - \alpha_{Si})(t - 25)) + C_2 (\varepsilon + (\alpha_{mat} - \alpha_{Si})(t - 25))^2 \right] \quad (3)$$

The coefficient of strain sensitivity at 25°C:

$$K_{\varepsilon,25} = C_1 + 2C_2 \cdot \varepsilon = \frac{\Delta R}{\Delta \varepsilon} \quad (4)$$

Dependence of coefficient of strain sensitivity to temperature:

$$K_{0,t} = C_1 \cdot \left(1 + \frac{B}{100} \cdot (t - 25) \right) \quad (5)$$

$$K_{\varepsilon,t} = K_{\varepsilon,25} \cdot \left(1 + \frac{B}{100} \cdot (t - 25)\right) \quad (6)$$

For gages with support:

Dependence of resistance to deformation:

$$R_{B\varepsilon,25} = R_{0,25} \cdot \left(1 + C_1 \cdot \varepsilon + C_2 \cdot \varepsilon^2\right) \quad (7)$$

Dependence of resistance to temperature for free gages does not state because semiconductor element is already glued on the support. For free semiconductor element applies the same formula as for the free gauge without support.

Dependence of resistance to deformation and temperature:

$$R_{\varepsilon,t} = R_{0,t} + R_{B0,25} \left[C_1 (\varepsilon + (\alpha_{mat} - \alpha_{Si})(t - 25)) + C_2 (\varepsilon + (\alpha_{mat} - \alpha_{Si})(t - 25))^2 \right] \quad (8)$$

The coefficient of strain sensitivity at 25°C:

$$K_{\varepsilon,25} = C_1 + 2C_2 \cdot \varepsilon = \frac{\Delta R}{\Delta \varepsilon} \quad (9)$$

Dependence of coefficient of strain sensitivity to temperature:


$$K_{0,t} = C_1 \cdot \left(1 + \frac{B}{100} \cdot (t - 25)\right) \quad (10)$$

$$K_{\varepsilon,t} = K_{\varepsilon,25} \cdot \left(1 + \frac{B}{100} \cdot (t - 25)\right) \quad (11)$$

- R_{0,25}.....Electrical resistance of the free gauge (without support) at 25°C [Ω]
- R_{B0,25}...Electrical resistance of the free gauge glued on the support at 25°C [Ω]
- R_{ε,25}....Electrical resistance of the deformed free gauge at 25°C [Ω]
- R_{Bε,25}...Electrical resistance of the deformed gauge glued on the underlay at 25°C [Ω]
- K_{ε,25}The coefficient of strain sensitivity at 25°C
- K_{ε,t}The coefficient of strain sensitivity at temperature t and deformation ε
- C₁.....Linear coefficient of deformation rate equation ^{*)}
- C₂.....Quadratic coefficient of deformation rate equation ^{*)}
- a,bTemperature coefficients of resistance free strain gauges
- BTemperature coefficient of strain sensitivity specified by the manufacturer [%/°C]
- εStrain [m/m]
- t.....Temperature [°C]
- α_{mat}Coefficient of thermal expansion material in which the strain gauge glued [1/°C]
- α_{Si}Coefficient of thermal expansion of silicon - 2.8×10⁻⁶ [1/°C]

^{*)} Constants C1, C2 are derived from changes in resistance strain gauges glued Cyanoacrylate glue. Epoxy glue hardened above 100°C transferred to the deformation strain gauge with higher efficiency. This increases C1 average value of 5% and the value of C2 average of 50%. The exact values are determined experimentally.

SAMPLES OF SOME TRANSDUCERS



F098 – Force sensor



L024 - Rope tension sensor



TQ051 – Calibrator torque



TQ045 – Torque sensor



C033 – Bending beam




F062 – Bending beam



M016 – Tensile sensor



M014 – Tensile sensor



F139 – Sensor memrane stress



F140 – Pressure sensor




F135, F136 – Adjustable pressure sensor



C020 – Pressure sensor

INDIVIDUAL APPLICATION OF STRAIN GAUGES



Tension in the chain



Test automotive lock




Loading rollers



Stress in the pressure cylinder



Shifter



Measuring of biting force